Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Gyan Bhibhakar

2 Name of Block/Road: - Aurai / Log2 Block Chowk to Halimbur (VR58)
(A) For Road:

(A) For Road:

- 1. Damage Location/Chainage :- 0-602100
- 2. Damage Length :- 0:42671cm 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:- Brack but (i)
- Equipment's/Tools being used in Restoration works:- Tractor (ii)
- Procedure taken up in Restoration works: (iii)
- Restored Length (iv) :- 0542676m

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्करपुर पूर्वी-1

GENERAL ABSTRACT L082 Block Chowk to Halimpur (VR58) Name of Road Muzaffarpur District Aurai Block Muzaffarpur East-2 Division Length of Road (in Km) 0.818 Km DESCRIPTION SI. No. **AMOUNT (LAKHS)** Earthwork 0.000 2 Jhama metal 3.514 Sand Filling 3 0.000 4 Sand bag 0.000 5 0.000 **GRAND SUB TOTAL** 3.514 TOTAL COST OF PROJECT IN LACS = 3.514

<u>Seq</u> 111121 JE

RWD

ASTITOMY

AE

RWD

EE TIL

Technically approved for RS 3,574 loc (Rypees three lac fifty one thousand four hundred only)

> ि ५%-\"। अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर