Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Cryan Vistanar

2 Name of Block/Road: - rings/mak sudbur to mustaglagan

(A) For Road:

- 1. Damage Location/Chainage :-(\(-965, 1015, 1101, 1133, 1303, 1428, 2705, 3600, 3850)
- 2. Damage Length :- 4200, 4320 and many places.
- 3. Nature of Damage :- 516.60m
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works:- Brien bets
- (ii) Equipment's/Tools being used in Restoration works:- Fractor
- Procedure taken up in Restoration works: (iii)
- Restored Length (iv) 516.60m

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) **Executive Engineer** R.W.D. Works Division Muzaffarpur East-1

AMOUNT (LAKHS)
23.648
0.000
0.000
0.000
23.648
23.648

ND RWD

Rev.

enty three low sixty five thousand only

K. M. D. May Cyrcle