

Inspection Report for flood Damage Work

Date :-

1. Name of PIU :- Sri. Jaimangal Rabidas, (R.W.D. Works Division, Banka-1)
2. Name of Block/ Road :- Belhar / Repair of Road Belhar Sandipi

A. For Road

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
i. Material being used in Restoration works :-
ii. Equipments/ Tools being used in Restoration works :-
iii. Procedure taken up in Restoration works :-
iv. Restored Length :-

B. For Bridge

1. Damage Location / Chainage :- Ch. – 2.700 Km to 2.760 Km
2. Damage Length :- 0.060 Km
3. Nature of Damage :- Abutment & deck slab has been destroyed.
4. Details of Restoration Works :-
i. Material being used in Restoration works :- Hume pipe, brick bat, moorum.
ii. Equipments/ Tools being used in Restoration works :- JCB, Tractor
iii. Procedure taken up in Restoration works :-
iv. Restored Length :- 0.060 Km

C. Requirement of new CD/ Bridge

- i. Name of Road :- Repair of Road Belhar Sandipi
ii. Location / Chainage :- 2.700 Km
iii. Type of CD work/ Length required :- RCC Culvert (6M x 3M)

- Upload one photograph of damage portion if available
- Attach minimum two photograph (during restoration & after restoration)
photographs should be Geotags and at least one photo be captured in selfie mode.

Signature of JE/AE/EE
16/12/2020
A.E.

Signature
16.12.2020
Executive Engineer
Rural Works Department
Works Division, Banka-1

Signature
16/12/20
(Name of Inspector)
R. W. D., W. D. Naugachia

Executive Engineer
R. W. D., W. D. Naugachia



SLD
 05/01/21 A/E
 05-01-2021
 A/E
 Lally
 5/13/2021
 Jtz

R. W. D., W. D. Naugachia
 Executive Engineer



16.12.20

16.12.2020
 A.E

16/12/20
 J.E

Executive Engineer
 R. W. D., W. D. Naugachia



S. Barua
 16/12/20
 Pritam
 16/12/2020
 N.E.
 Latup
 16/12/2020
 N.E.
 16/12/2020
 Executive Engineer
 R. W. D., W. D. Naugachia



Labels
 16.12.20

Priyam
 16.12.2020
 A/E

Label
 16/12/2020
 J/S

K.P. 16/12/20
 Executive Engineer
 R. W. D., W. D. Naugachia