

Inspection Report for flood Damage Work

Date :-

1. Name of PIU :- Sri. Jaimangal Rabidas, (R.W.D. Works Division, Banka-1)
2. Name of Block/ Road :- Fullidumar / L068 Samukhiya More to Kadbara (Track 68)

A. For Road

1. Damage Location / Chainage :- 0.102 Km to 0.160 Km
2. Damage Length :- 0.058 Km
3. Nature of Damage :- Shoulder & Road Crust has been damaged.
4. Details of Restoration Works
i. Material being used in Restoration works :- Brick bat , moorum and bamboo
ii. Equipments/ Tools being used in Restoration works :- JCB, Tractor
iii. Procedure taken up in Restoration works :-
iv. Restored Length :- 0.058 KM


B. For Bridge


1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
i. Material being used in Restoration works :-
ii. Equipments/ Tools being used in Restoration works :-
iii. Procedure taken up in Restoration works :-
iv. Restored Length :-


C. Requirement of new CD/ Bridge

- i. Name of Road :-
ii. Location / Chainage :-
iii. Type of CD work/ Length required :-

- Upload one photograph of damage portion if available
- Attach minimum two photograph (during restoration & after restoration)
photographs should be Geotags and at least one photo be captured in selfie mode.


16/12/2020
Signature of JE/AE/EE
Pritam
16.12.2020
A.E


16.12.2020
Executive Engineer
Rural Works Department
Works Division, Banka-1


16/12/2020
Signature
(Name of Inspector)
RAHMSAHSIT PRASAD.

Executive Engineer
R. W. D., W. D. Naugachia



Selidar
16.12.20

Pritam
16.12.2020
A/E

call
16/12/2020
A/E

R. W. D.
16/12/20

Executive Engineer
R. W. D., W. D. Naugachia



[Signature]
 04.07.21

[Signature]
 04.01.2021
 A.E

[Signature]
 04/1/2021

[Signature]
 4/01/21
Executive Engineer
 R. W. D., W. D. Naugachia



S. W. D.
 16/12/20

Pritham
 16/12/2020
 A/E

Callu
 16/12/2020
 A/E

R. W. D.
 16/12/2020
 Executive Engineer
 R. W. D., W. D. Naugachia