# **Inspection Report for Flood Damage Work**

#### Date:-

1 Name of PIUs: - Cyan Vivalcon

2 Name of Block/Road: - Aurai | Pramevor to Rampur

# (A) For Road:

- :- many places. :- 0.6375 Km 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works: - Brick bats
- (ii) Equipment's/Tools being used in Restoration works:- Tractor
- Procedure taken up in Restoration works: (iii)
- (iv) Restored Length :- 0.0375 Km

### (B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजक्फरपुर पूर्वी-1

## **GENERAL ABSTRACT**

Name of Road

Pramjevar to Rampur

District

Muzaffarpur

Block

Aurai

**Division** 

Muzaffarpur East-2

Length of Road (in Km)

2.000 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
· 1	Jhama metal	3 17
2	Sand Filling	0.00
3	Sand bag	0.00
4	H.P.	0.00
	GRAND SUB TOTAL	3,17
TOTAL (	COST OF PROJECT IN LACS =	2 ***

11/01/21

JE

RWD

AG MOIM

\_\_\_

RWD

EE

DIAID

Technically approved for RS 3.17 lac.
(Rupees three lac seventeen thousand only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग

कार्य अंचल,मुजप्फरपुर