

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Aurai / Mahua Chowk to Balia

### (A) For Road:

1. Damage Location/Chainage :- 0.820 km
2. Damage Length :- 0.02943 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brick bats
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.02943 km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
25.1.21  
Signature

(Name of Inspection)

कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1



### GENERAL ABSTRACT

Name of Road Mahua Chowk to Balia

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km)

2.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.385
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.385
TOTAL COST OF PROJECT IN LACS =		1.385

सुय  
11/11/21  
JE  
RWD

11/11/21  
AE  
RWD

9/11/21  
EE  
RWD

Technically approved for 1.385 lac  
(Rupees one lac thirty eight thousand five hundred only)

अधीक्षण अभियंता  
ग्रामीण कार्य विभाग  
कार्य अंचल, मुजफ्फरपुर