## Inspection Report for Flood Damage Work

## Date:

- 1. Name of PIUs (nyam withakers
- 2. Name of Block/Road Kcutsa / Agahari to Tehward path

A For Road

- 1. Damage Location/Chainage
- : 0:030km, 0:200km, 0:250km, 0:500km, 0:6001km
- 2. Damage Length
- : 0.9058Km

0, 900 lom, 0, 990 lon, 1 'Siem

- 3. Nature of Damage
- 4. Details of Restoration Works
  - Material being used in Restoration works: Brick ball
  - Equipments/Tools being used in Restoration works: ii.
  - Procedure taken up in Restoration works: ili.
  - iv. Restored Length
- : 0.9058 Km

## R. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
  - Material being used in Restoration works: i.
  - Equipments/Tools being used in Restoration works: ii.
  - Procedure taken up in Restoration works: iii.
  - iv. Restored Length

Signature of JE/AE/EE

Light fure

(Name of Inspector)

·EE

RWD WOODL DIVISION muzaffaxpur Gerst-1

## **GENERAL ABSTRACT**

Name of Road

Agahari to Tehwara Path

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

2.880 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.526
, 2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	1.526
TOTAL	COST OF PROJECT IN LACS =	1.526

Sy 1.53 lac

100

RWD

17:12

ΑE

RWD

EE '

RWD

Technically approved soo RS 1.53 lac.
(Rubees one lac sisty three thousand only)

अधीक्षण डिभियंता शिपीण प्रमिषं विभागीट कार्य अंच्रा स्मामानुपुर