

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Basantpur to Chardewali (VR 42)
 Hazards: Flood/Rain - Flood in 2020-21.
 Division: Bagha - I District: West Champaran Actual Length (in km): 2.199 Km.
 Damage Length (in km): 0.550 Km. Damages Location/Chainage: 0 to 550 m.

Name of Scheme/Programme: PMGSY
 Status of Project: Under Agreement/Out of Agreement Under Agreement.

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	

Description of observation : In permanent Restoration of 0.550 Km throughout MSS surface done.

b)	Adequate Thickness of pavement layers constructed	
----	---	--

Description of observation : only pot patch with GSB go II & WBM go III done as and where required.

c)	Quality of Construction Material Used	
----	---------------------------------------	--

Description of observation : Material Satisfactory

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
----	---	--

Description of observation : No undulation in MSS surface.

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation : No rain cuts.

2	Cross Drainage Structure	N.A
---	--------------------------	-----

a)	Condition of head walls in Hume pipe culverts	
----	---	--

b)	Condition of Vent Clearance	
----	-----------------------------	--

c)	Condition of railings/Slab/approach for Bridges	
----	---	--

Description of observation of CD works : —


Remark if any: This road is again flooded with rain water in some parts in this current month as told by villagers.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S (Satisfactory)
---------------------------------------	------------------

Name of Officer: Rana Barun Kumar Singh

Designation: Executive Engineer


 22.06.2021
 (Signature)