

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: T.I N.H.-31 To Kurban Chowk

Hazards: Flood/Rain

Division: Baizi

District: Purnia

Actual Length (in km): 1.727

Damage Length (in km): 0.084 km

Damages Location/Chainage: 0.330km, 0.950km, 1.369km

Name of Scheme/Programme: FDR (3054)

Status of Project: Under Agreement/Out of Agreement

Remarks : (S/U)

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	S

Description of observation : MSS Surfacing work is in good condition

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation : G.S.B - Gr II - 175mm  
W.B.M Gr II - 75mm  
W.B.M Gr III - 75mm  
MSS - 20mm

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation : Good quality material used .

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A.
----	---	------

Description of observation : N.A.

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation : Flank work in progress

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	S
b)	Condition of Vent Clearance	S
C)	Condition of railings/Slab/approach for Bridges	N.A

Description of observation of CD works : Found in good condition

Remark if any: work is in good condition

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Ratnesh Paswan

Designation: E.E.

23-6-21  
(Signature)

At Kumar  
23/06/21  
A.E.