

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *Tarwalia - Pachgaon*

Hazards: *Flood/Rain* *Flood*

Division: *Bozha - 1* District: *West Champaran* Actual Length (in km): *5.496*

Damage Length (in km): *0.010* Damages Location/Chainage: *1550 to 1560*

Name of Scheme/Programme: *PMBSY*

Status of Project: *Under Agreement/Out of Agreement* *Under agreement*

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
---------	--	-----------------

1.	Pavement (BT/CC)	<i>S</i>
----	------------------	----------

a)	Condition of Surfacing	
----	------------------------	--

Description of observation : *only R.C.C. slab culvert of size 2x1.5m done recently for the clearance of water logged due to flood.*

b)	Adequate Thickness of pavement layers constructed	
----	---	--

Description of observation : *—*

c)	Quality of Construction Material Used	
----	---------------------------------------	--

Description of observation : *—*

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
----	---	--

Description of observation : *No surface cracks.*

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation : *—*

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	
----	---	--

b)	Condition of Vent Clearance	
----	-----------------------------	--

c)	Condition of railings/Slab/approach for Bridges	
----	---	--

Description of observation of CD works : *slab culvert condition is satisfactory.*

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

*Satisfactory (S)*

Name of Officer: *Rana Babun Kumar Singh*

Designation: *Executive Engineer.*

*23.06.2021*  
(Signature)