

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Kur sakanta Hatha chowk to Forbesganj via Degra Boudh		
Hazards	Flood/Rain	1 Flood
Division: Forbesganj	District: Arona	Actual Length (in km): 1.50
Damage Length (in km): 0.950	Damages Location/Chainage:	
Name of Scheme/Programme:	FDR 3054	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	—
a)	Condition of Surfacing	—
Description of observation : Permanent Restoration work not executed.		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	—
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Assistant Remark if any: Executive Engineer Forbesganj told that this Road sanctioned in PM Aay Phase-II under work Division Arona and work started. So Restoration work not done		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Name of Officer: Bindeu Rajak

Designation: Executive Engineer
R.W.D.
Regional Laboratory Darbhanga

24/06/21
A.E.

(Signature) 24/06/21