

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *Banwari Baghlya to Champapur path.*

Hazards

Flood/Rain *Flood in 2020-21*

Division: *Bagha - 1*

District: *Wkt Champaran*

Actual Length (in km): *1.1 km.*

Damage Length (in km): *—*

Damages Location/Chainage: *—*

Name of Scheme/Programme:

OLD SCHEME

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

Description of observation : *In this road I could not reach due to many rivers and their parts (approximately Twenty) which is flooded.*

b)

Adequate Thickness of pavement layers constructed

Description of observation :

c)

Quality of Construction Material Used

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

e)

Compaction of flanks/ slope & raincuts

Description of observation :

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

C)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: *Permanent Restoration point could not allow due to flood in river and part to reach the main road location.*

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Name of Officer:

Rana Babin Kumar Singh.

Designation:

Executive Engineer.

(Signature)

24.06.2024