

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>MIRZAPUR TO PURIYA</u>			
Hazards		Flood/Rain	
Division: <u>BARSOI</u>	District: <u>KATIHAR</u>	Actual Length (in km): <u>1.40</u>	
Damage Length (in km): <u>1.40 km</u>	Damages Location/Chainage:		
Name of Scheme/Programme: <u>FDR</u>			
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC) <u>BT</u>		
a)	Condition of Surfacing		<u>S</u>
Description of observation : <u>No defect</u>			
b)	Adequate Thickness of pavement layers constructed		<u>S</u>
Description of observation : <u>BT. layer - 20mm. (PMC)</u>			
c)	Quality of Construction Material Used		<u>S</u>
Description of observation : <u>Good.</u>			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		<u>S</u>
Description of observation : <u>No defect</u>			
e)	Compaction of flanks/ slope & raincuts		<u>S</u>
Description of observation : <u>At few place, Raincut found, Needs to be Repaired</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		<u>—</u>
b)	Condition of Vent Clearance		<u>—</u>
c)	Condition of railings/Slab/approach for Bridges		<u>—</u>
Description of observation of CD works : <u>NA</u>			
Remark if any: <u>—</u>			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer: MAHESH PD GUPTA

Designation: E.E.,
RWD, Regional Lab.
Purnea

23/06/2021
(Signature)