

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: BHUTANI TO LOKHAR PATH

Hazards

Flood/Rain

Division: SITAMARHI

District: SITAMARHI

Actual Length (in km): 4.82

Damage Length (in km): 0.280

Damages Location/Chainage: 0.380, 0.430, 0.485, 1.325, 3.33, 3.49
3.55, 3.725, 3.85

Name of Scheme/Programme:

F.D.R

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/U)

1.

Pavement (BT/CC)

BT

a)

Condition of Surfacing

S

Description of observation:

M53 Surfacing found in good condition.

b)

Adequate Thickness of pavement layers constructed

S

Description of observation:

Adequate thickness found.

c)

Quality of Construction Material Used

S

Description of observation:

Good quality material used.

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation:

NA

e)

Compaction of flanks/ slope & raincuts

Description of observation:

Flank work in progress.

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

S

b)

Condition of Vent Clearance

S

c)

Condition of railings/Slab/approach for Bridges

NA

Description of observation of CD works:

Found in good condition.

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR DAS

Designation: E.E.

24/06/24
A.E.

Signature