

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: LALBANDI PURBI PATERWA TO BACCHAURA		
Hazards	Flood/Rain	
Division: SITAMARHI	District: SITAMARHI	Actual Length (in km): 8.149
Damage Length (in km): 0.190 km	Damages Location/Chainage: 5.3 & 5.6	
Name of Scheme/Programme:	F.D.R.	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	BT
a)	Condition of Surfacing	S
Description of observation: MSS Surfacing found in good Condition.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation: Adequate thickness found.		
c)	Quality of Construction Material Used	S
Description of observation: Good quality material used.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation: NA		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation: Condition of flank is good.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	S
b)	Condition of Vent Clearance	S
c)	Condition of railings/Slab/approach for Bridges	NA
Description of observation of CD works: CD work found in good Condition.		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

24/06/21
A.E.

24/6/21
(Signature)