

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: MADHIA GHUGHURATO JHAMUANA JAINAGAR VIA ARARIA N.H-77

Hazards Flood/Rain

Division: SITAMARHI District: SITAMARHI Actual Length (in km): 5.75

Damage Length (in km): 0.110 Damages Location/Chainage: 3.9, 4.025 & 0.550

Name of Scheme/Programme: F.D.R

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) BT	
a)	Condition of Surfacing	S

Description of observation : MSS Surfacing found in good Condition.

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation : Adequate thickness found.

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation : Good quality material used.

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
----	---	--

Description of observation : NA

e)	Compaction of flanks/ slope & raincuts	S
----	--	---

Description of observation : Condition of flank is good.

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	S
----	---	---

b)	Condition of Vent Clearance	S
----	-----------------------------	---

c)	Condition of railings/Slab/approach for Bridges	NA
----	---	----

Description of observation of CD works : CD Found in good Condition.

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'S'

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

24/06/21
A.E.

24/6/21
(Signature)