

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *LD 58- Belwaria Mill road to Sapahi*

Hazards

Flood/Rain *Flood in 2020-21*

Division: *Rashid-1*

District: *West Champaran*

Actual Length (in km): *4.056*

Damage Length (in km): *0.008*

Damages Location/Chainage: *2.800 to 2.808 Km*

Name of Scheme/Programme:

PMGSY

Status of Project:

Under Agreement/Out of Agreement *Under Agreement*

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

S

Description of observation :

one RCC Culvert of size 2X1.5m done at pavement Restoration point.

b)

Adequate Thickness of pavement layers constructed

Description of observation :

c)

Quality of Construction Material Used

Description of observation :

Quality of culvert material is satisfactory

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

No Surface Cracks.

e)

Compaction of flanks/ slope & raincuts

Description of observation :

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

Satisfactory

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

RCC Culvert of size 2X1.5m is newly constructed at Restoration point.

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer *Rana Ramesh Kumar Singh.*

Designation: *Executive Engineer.*

26.06.2021
(Signature)