

0.830	0.300	20.5000
0.000	0.197	1.6700
		1.1400

INSPECTION REPORT

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Chikni Paswan Tola Bypass to Dahabatti Bypass Sakhal Pakki

Hazards: Flood/Rain

Division: Phulparan District: Madhubani Actual Length (in km): 2.00 Km

Damage Length (in km): 0.12 Km Damages Location/Chainage: Ch 0.45 Km to 0.57 Km, 2

Name of Scheme/Programme: Ch 0.60 Km to 0.66 Km

Status of Project: Under Agreement/Not Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks

1. Pavement (BT/CC) BT

a) Condition of Surfacing Satisfactory

Description of observation :

b) Adequate Thickness of pavement layers constructed YES

Description of observation :

c) Quality of Construction Material Used Good

Description of observation :

d) Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. —

Description of observation :

e) Compaction of flanks/ slope & raincuts In Progress

Description of observation :

2. Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts NA

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U) Satisfactory

Name of Officer: Ram Kumar Mishra

Designation: E.E, Rlab Gulzarbag Paha