

		1.200	22.93000
		12.470	0.500
		3.300	0.200
		0.830	0.197
		2.000	0.120

INSPECTION REPORT FOR

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD			
Name of Scheme:	Narratiya Bazar NH 57 to Supaul Zila Sama Bhadra Parva Railwaar Halt, Hathi, Samraat, Karmali.		
Hazards	Flood/Rain		
Division :	Phulbazar	District: Madhubani	Actual Length (in km):
Damage Length (in km):	1.00 Km.	Damages Location/Chainage: Ch 2.5 Km to 3.61 Km. Ch 7.5 Km to 8.43 Km.	
Name of Scheme/Programme:			
Status of Project:	Under Agreement / Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		BT
a)	Condition of Surfacing		satisfactory
Description of observation :			
b)	Adequate Thickness of pavement layers constructed		YES
Description of observation :			
c)	Quality of Construction Material Used		Good .
Description of observation :			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.		—
Description of observation :			
e)	Compaction of flanks/ slope & raincuts		In progress.
Description of observation :			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		NA
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works :			
Remark if any:			
Overall Rating		Satisfactory (S) / Unsatisfactory (U)	
		Satisfactory	
Name of Officer:	Ram Kumar Mishra		
Designation:	E.E R.Lab Ghatgarh Path		

(Signature) 10/10/2021