

Chakras Purnima Tola	0.810	0.200	20.56800
Chakras Purnima Tola	0.810	0.197	7.67700
Chakras Purnima Tola	2.000	0.120	7.34800

INSPECTION REPORT FOR FLOOD / RAIN DAMAGE ROAD

/RAIN DAMAGE

Actual Length (in km)

age:

ration work

ed

INSPECTION REPORT FOR FLOOD / RAIN DAMAGE ROAD

Name of Scheme:	Bairya to Phulparas		
Hazards	Flood/Rain		
Division:	Phulparas	District:	Madhubani
Damage Length (in km):	1.00 Km.	Actual Length (in km):	7.45 Km.
Name of Scheme/Programme:	Damages Location/Chainage: Ch 3.5 Km to 4.0 Km. Ch 4.5 Km to 5.0 Km.		
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		BT.
a)	Condition of Surfacing		Satisfactory

Description of observation :

b)	Adequate Thickness of pavement layers constructed	YES
----	---	-----

Description of observation :

c)	Quality of Construction Material Used	Good.
----	---------------------------------------	-------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
----	---	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	in progress
----	--	-------------

Description of observation :

2	Cross Drainage Structure	] NA
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra.

Designation:

E.E, R Lab Gulzarbag Patna.

(Signature)

25/06/2020