

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Uccalth to Pokhravhi

Hazards Flood/Rain

Division: Benipatti District: Madhubani Actual Length (in km): 2.66km

Damage Length (in km): 0.064 Damages Location/Chainage: 0-080, 0-110, 0-125 km, 1.100, 3.200 km

Name of Scheme/Programme: Restoration

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
---------	--	-----------------

1.	Pavement (RT/CC)	
----	------------------	--

a)	Condition of Surfacing	S
----	------------------------	---

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation :

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	No
----	---	----

Description of observation :

e)	Compaction of flanks/ slope & raincuts	No
----	--	----

Description of observation :

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	
----	---	--

b)	Condition of Vent Clearance	
----	-----------------------------	--

c)	Condition of railings/Slab/approach for Bridges	
----	---	--

Description of observation of CD works :

Remark if any:

Flood Damage Surface Portion is good condition after work

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Sri Kant Prasad
Name of Officer:

Designation: E.E.

23/06/21

23/6/2021
(Signature)