

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: Phulbari Haliya to Kshatigraat PCC Road Madhya vidyalaya		
Hazards	Flood/Rain	
Division : Balas	District: Purne	Actual Length (in km): 0.600 km
Damage Length (in km): 0.066 km	Damages Location/Chainage: 0.175 km, 0.230 km	
Name of Scheme/Programme:	FDR(3054)	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) CC	S
a)	Condition of Surfacing	S
Description of observation : CC Pavement surface is in good condition		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : CC Pavement - 190mm		
c)	Quality of Construction Material Used	S
Description of observation : Good quality material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	N.A.
Description of observation : N.A.		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Flank work in progress		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N.A.
b)	Condition of Vent Clearance	N.A.
C)	Condition of railings/Slab/approach for Bridges	N.A.
Description of observation of CD works : N.A.		
Remark if any: Work is in good condition		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ratnesh Paswan

Designation: E.E.

24/6/21  
(Signature) 24-6-21  
E.E.

24/06/21