INSPECTION	N REPORT FOR FLOOD /RAIN DAMAGE I	ROAD
	i to Rampur	
Hazards	Flood/Rain	
Division: Baisi	District: Purnea Actual Length (in km): 2-860 km	
Damage Length (in km): D. O.		
Name of Scheme/Programme:	FDR (3054)	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC) 87	S
a)	Condition of Surfacing	5
Description of observation:	55 Surfacing work is in good condition	
b)	Adequate Thickness of pavement layers constructed	S
Description of observation:	GSB CT-II - 175mm WBM CT-II - 75mm WBM CT-III - 75mm MSS - 20mm	
e)	Quality of Construction Material Used	S
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N. A.
Description of observation :	M.A.	
e)	Compaction of flanks/ slope & raincuts	
Description of observation :	Flank work in progress	
2	Cross Drainage Structure	,
a)	Condition of head walls in Hume pipe culverts	8
b)	Condition of Vent Clearance	S
C)	Condition of railings/Slab/approach for Bridges	N.A.
Description of observation of C Remark if any:	CD work found in good condition	
Work	is an good condition	
Overall Rating		
	Satisfactory (S) / Unsatisfactory (U)	C

Name of Officer: Ratnesh Paswan

Designation: E.E.

24/06/21

(Signature)

STORE PER BUILDER WITH BUILDING BENEATH ON