

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: TS PWD TO Shadipur Bhutha		
Hazards	Flood/Rain	
Division : Balas	District: Purnea	Actual Length (in km): 2.840 km
Damage Length (in km): 0.098 km	Damages Location/Chainage: 1.280 km, 1.920 km	
Name of Scheme/Programme:	FDR(3054)	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) BT	S
a)	Condition of Surfacing	S
Description of observation : MSS Surfacing work is in good condition		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : GSB Gr II - 175 mm WBM Gr II - 75 mm WBM Gr III - 75 mm MSS - 20 mm		
c)	Quality of Construction Material Used	S
Description of observation : Good quality material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A.
Description of observation : N.A.		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Flank work in progress		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	S
b)	Condition of Vent Clearance	S
C)	Condition of railings/Slab/approach for Bridges	N.A.
Description of observation of CD works : CD work found in good condition		
Remark if any: width of road is found 3.40m at different point.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ratnesh Paswan

Designation: E.E.

Ratnesh
24/06/21
A.E.

Ratnesh
24.6.21
(Signature)
E.E.