

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: FATEHPUR SARBARPUR MARPA BETAH KANHAULI BHASHAR PATH

Hazards Flood/Rain

Division: SITAMARHI District: SITAMARHI Actual Length (in km): 8.72

Damage Length (in km): 0.170 Damages Location/Chainage: 0.370, 0.390, 0.425, 0.730.

Name of Scheme/Programme: F.D.R.

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)

1. Pavement (BT/CC) BT

a) Condition of Surfacing S

Description of observation: Condition found in good Shape.

b) Adequate Thickness of pavement layers constructed

S

Description of observation: Adequate thickness found

c) Quality of Construction Material Used

S

Description of observation: Good quality of Material used.

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation:

NA

e) Compaction of flanks/ slope & raincuts

Description of observation:

Flank work in Progress.

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

S

b) Condition of Vent Clearance

S

c) Condition of railings/Slab/approach for Bridges

NA

Description of observation of CD works:

CD work found in good Condition.

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

24/06/21
A.E.

24/6/21
(Signature)