

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: ITHARWA DULARPUR TO MURHA CHHATAUNA

Hazards Flood/Rain

Division: SITAMARHI District: SITAMARHI Actual Length (in km): 5.83

Damage Length (in km): 0.135 Damages Location/Chainage: 0.360, 0.730, 0.780, 0.815, 1.15, 1.180

Name of Scheme/Programme: F.D.R.

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)

1. Pavement (BT/CC) BT
a) Condition of Surfacing S

Description of observation: MSS Surfacing found in good condition.

b) Adequate Thickness of pavement layers constructed S

Description of observation: Adequate Thickness found

c) Quality of Construction Material Used S

Description of observation: Good quality of material used

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation: NA

e) Compaction of flanks/ slope & raincuts

Description of observation: Flank work in Progress.

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts S

b) Condition of Vent Clearance S

c) Condition of railings/Slab/approach for Bridges NA

Description of observation of CD works: CD work found in good condition.

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

24/6/21
A.E.

24/6/21
(Signature)