

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: PWD Gathi - Lakshmanpur
 Hazards: Flood/Rain Flood in 2020-21

Division: Bagha - 1 District: West Champaran Actual Length (in km): 8.092

Damage Length (in km): Approx. 0.100 Damages Location/Chainage: Approx. 6.6 to 6.7 km

Name of Scheme/Programme: PMHSP

Status of Project: Under Agreement/Out of Agreement Out of Agreement Remarks: (S/U)

Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	

Description of observation: In approx. 100m length of this road 20mm M.S.S done throughout.

b)	Adequate Thickness of pavement layers constructed	
----	---	--

Description of observation: Pot patch with LBSG II and WBMG III.

c)	Quality of Construction Material Used	
----	---------------------------------------	--

Description of observation: M.S.S material quality is satisfactory.

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
----	---	--

Description of observation: No Undulation

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation: No rain cuts.

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	
----	---	--

b)	Condition of Vent Clearance	
----	-----------------------------	--

c)	Condition of railings/Slab/approach for Bridges	
----	---	--

Description of observation of CD works: —

Remark if any: In this Road some parts (approx. 50m length) also damaged due to current rain in this season (June 2021) which is fully water logged.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: Rana Brij Kumar Singh

Designation: Executive Engineer.

25.06.2021
(Signature)