

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <i>LO64 - PWD Narkatyaganj launiga to Baiti Martianiya</i>		
Hazards	Flood/Rain <i>Flood in 2020-21</i>	Actual Length (in km): <i>2.002</i>
Division: <i>Ragha - I</i>	District: <i>West Champaran</i>	Damages Location/Chainage: <i>Approx. 1.10 to 1.36 Km</i>
Damage Length (in km): <i>Approx 0.260</i>		
Name of Scheme/Programme: <i>PMGSY</i>		
Status of Project: <i>Under Agreement/Out of Agreement Under Agreement</i>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CE)	
a)	Condition of Surfacing	<i>S</i>
Description of observation : <i>In approximately 260m length, of this road 20mm M.S.S done throughout.</i>		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : <i>Pot patch with G.B.Gs II & W.B.M.Gs III.</i>		
c)	Quality of Construction Material Used	
Description of observation : <i>MSS Material Quality is Satisfactory.</i>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation : <i>No Undulation.</i>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <i>No raincuts.</i>		
2	Cross Drainage Structure	<i>-</i>
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works : <i>-</i>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: *Rana Borsun Kumar Singh*
Designation: *Executive Engineer.*

25.06.2021
(Signature)