

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Pranhpur NH-57 to Pirogach.</u>	
Hazards	Flood/Rain
Division : <u>Phulparas</u>	District: <u>Madhubani</u>
Damage Length (in km): <u>1.50 Km</u>	Actual Length (in km): <u>7.830 Km.</u>
Name of Scheme/Programme:	Damages Location/Chainage:
Status of Project:	Under Agreement/Out of Agreement
Sr. No.	Parameters to be Checked in Restoration work
1.	Pavement (BT/CC)
a)	Condition of Surfacing
Remarks : (S/S)	
<u>BT.</u>	

Description of observation : Surface of pavement is damaged at different points in village portion.

b)	Adequate Thickness of pavement layers constructed	<u>YES.</u>
----	---	-------------

Description of observation :

c)	Quality of Construction Material Used	<u>Good.</u>
----	---------------------------------------	--------------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>—</u>
----	---	----------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	<u>in progress.</u>
----	--	---------------------

Description of observation :

Cross Drainage Structure	
2	Condition of head walls in Hume pipe culverts
a)	Condition of Vent Clearance
b)	Condition of railings/Slab/approach for Bridges
C)	

Description of observation of CD works :

Remark if any: Surface of pavement is damaged at different points in village portion.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>Unsatisfactory</u>
---------------------------------------	-----------------------

Name of Officer: Ram Kumar Mishra.
Designation: E.E., R Lab Gulzarbaghatna

(Signature)