INSPECTIO	ON REPORT FOR FLOOD /RAIN DAMAGE	ROAD
Name of Scheme: AUng	i to khikhari Palli	E STATE OF THE STA
Hazards	Flood/Rain	
Division: Beni Patti	District: Modbubawi Actual Length (in km): 2 (62	
Damage Length (in km): 0.3	93 Damages Location/Chainage: 0.400, 1.50	
Name of Scheme/Programme:	Restoration	YERSON INC.
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1,	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation:		
b)	Adequate Thickness of pavement layers constructed	5
Description of observation :		3
Description of observation :	Quality of Construction Material Used	S
d)	Whether free from any defects and Irregularity example-	
	Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
e) Description of observation :	Compaction of flanks/ slope & raincuts	- 20139
2	CONTRACTOR OF THE PROPERTY OF	
a)	Cross Drainage Structure	The second second
a)	Condition of head walls in Hume pipe culverts Condition of Vent Clearance	
C)	· · · · · · · · · · · · · · · · · · ·	
Description of observation of C	Condition of railings/Slab/approach for Bridges	
Remark if any:	Damage Portion abter work surface	continu
Overall Rating		STATIFICA.
	Satisfactory (S) / Unsatisfactory (U)	S
Sin Kaut prased. Name of Officer:		03/2
Designation: E-E.	(Si	23 6 202 gnature)

R.L- Saharna.