

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Bengang to Pokhrani

Hazards Flood/Rain

Division: Benifatti District: Madhubani Actual Length (in km): 1.153 km

Damage Length (in km): 0.061 km Damages Location/Chainage: 0.700, 1.020 km

Name of Scheme/Programme: Restoration

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>

Description of observation :

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
----	---	----------

Description of observation :

c)	Quality of Construction Material Used	<u>S</u>
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>-</u>
----	---	----------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	<u>-</u>
----	--	----------

Description of observation :

2	Cross Drainage Structure	<u>-</u>
a)	Condition of head walls in Hume pipe culverts	<u>-</u>
b)	Condition of Vent Clearance	<u>-</u>
C)	Condition of railings/Slab/approach for Bridges	<u>-</u>

Description of observation of CD works :

Remark if any:

Damage portion after work surface is good condition

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Sri Kant Prasad

Name of Officer:

Designation: E.E.

24/06/21

24/6/2021
(Signature)