

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: To 2 to Sirwana

Hazards Flood/Rain

Division: Benipatti District: Madhubani Actual Length (in km): 8.276 km

Damage Length (in km): 0.208 km Damages Location/Chainage: 6.900, 7.200 km

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

Description of observation :

b)

Adequate Thickness of pavement layers constructed

Description of observation :

c)

Quality of Construction Material Used

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

e)

Compaction of flanks/ slope & raincuts

Description of observation :

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Two 2 no, Rcc slab culverts work in progress and approach in progress.

Remark if any:

Work in progress.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Sri Kant Prasad

Name of Officer:

Designation: E.E.

24/06/21

24/6/2021
(Signature)