

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: 103 To Pamlaghat		
Hazards: Flood/Rain		
Division: Benipatti	District: Madhubani	Actual Length (in km): 1.965 km
Damage Length (in km): 0.121 km	Damages Location/Chainage: 0.200, 0.200 km	
Name of Scheme/Programme: Restoration		
Status of Project: Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	—
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Remark if any: Damage portion after work surface is good condition		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Sri Kant Prasad

Name of Officer:

Designation: E.E.

23/06/21

23/6/2021
(Signature)