

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Lo 39 To South Bishanpur</u>		
Hazards	Flood Rain	
Division: <u>Boni Patti</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>1.613 km</u>
Damage Length (in km): <u>0.007 km</u>	Damages Location/Chainage: <u>0.700 km</u>	
Name of Scheme/Programme:	<u>Restoration</u>	
Status of Project:	Under Agreement Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	S
Description of observation of CD works :		
<u>Rec slab culvert work in progress and approach in progress</u>		
Remark if any:		
<u>Work in Progress.</u>		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)

Sri Kant Prasad
Name of Officer:

Designation: E.E.

24/06/24

24/6/24
(Signature)