

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: SH-52 To Palli Reg Road

Hazards Flood/Rain

Division: Benipatti

District: Madhubani

Actual Length (in km):

Damage Length (in km): 0.122

Damages Location/Chainage: 0.090, 0.110 km, 0.130, 0.300 km

Name of Scheme/Programme:

Restoration

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

S

Description of observation :

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

c)

Quality of Construction Material Used

S

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

—

Description of observation :

e)

Compaction of flanks/ slope & raincuts

—

Description of observation :

2

Cross Drainage Structure

—

a)

Condition of head walls in Hume pipe culverts

—

b)

Condition of Vent Clearance

—

c)

Condition of railings/Slab/approach for Bridges

—

Description of observation of CD works :

Remark if any:

after work  
Damage Portion A Surface is good Condition

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Sri Kant Prasad

Name of Officer:

Designation: E.E.

23/06/21

23/6/2021  
(Signature)