INSPECTION	REPORT FOR FLOOD/RAIN DAMAGE	ROAD
Name of Scheme: Jankin	Marto Brahmpuni	MODEL STATE OF THE STATE OF
Hazards	Flood/Rain	
Division: Benifotti	District: Madhubani Actual Length (in km): 1.882 KM	
	66 km Damages Location/Chainage: 0.045km	The same of the sa
Name of Scheme/Programme:	Restoration	CONTRACTOR OF THE PROPERTY AND
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	Color Color Color State
Description of observation:		
b)	Adequate Thickness of pavement layers constructed	l'e
	& W.B.M-III	
Description of observation :	Quality of Construction Material Used	S
d)	Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Payement, Poor workmanship, etc.	
A	Compaction of floring lands	
e) Description of observation :	Compaction of flanks/ slope & raincuts	(1)
Description of observation:		
	Cross Drainage Structure	Commence in the second of
a)	Condition of head walls in Hume pipe culverts	The state of the s
b)	Condition of Vent Clearance	409;222425
C)	Condition of railings/Slab/approach for Bridges	A STATE OF S
Description of observation of CD		
Remark if any:	B.T Work hot done.	
Overall Rating		
L	Satisfactory (S) / Unsatisfactory (U)	S
Sin Kaut Praced Name of Officer: Designation: E:E	2	3/6/2021