

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: SH 52 Rajaswa Kachari to Benipatti Akaur Path

Hazards: Flood/Rain

Division: Benipatti District: Madhubani Actual Length (in km): 0.650 km

Damage Length (in km): 0.089 km Damages Location/Chainage: 0.195 km

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation :

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
----	---	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	---

Description of observation :

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
C)	Condition of railings/Slab/approach for Bridges	—

Description of observation of CD works :

Remark if any:

Damage Portion after work Surface good condition.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Sri Kant Prasad

Name of Officer:

Designation: E.E.

25/06/21
MS

313
25/6/2021
(Signature)