

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *PWD Bagha Silwanaria - Kateriya*

Hazards

Flood/Rain *Flood in 2020-21*

Division: *Bagha-1*

District: *West Champaran*

Actual Length (in km): *4.100*

Damage Length (in km): *Approx. 0.215*

Damages Location/Chainage: *Approx. 1.800 to 2.015 km*

Name of Scheme/Programme:

PMGSY

Status of Project:

Under Agreement/Out of Agreement *out of Agreement*

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/EC)

a)

Condition of Surfacing

S

Description of observation :

In approximately 215m length of this road 20mm MSS done throughout.

b)

Adequate Thickness of pavement layers constructed

Description of observation :

Not path with GSB go II and WBM go II

c)

Quality of Construction Material Used

Description of observation :

MSS material quality is satisfactory

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

No Undulation.

e)

Compaction of flanks/ slope & raincuts

Description of observation :

No raincuts.

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: *Rana Basu Kumar Singh*

Designation: *Executive Engineer*

25.06.2021
(Signature)