

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Abadpur Se Harnaroi Kripara Jarnaria sohar

Hazards: Flood/Rain

Division: Barsoi

District: Katihar

Actual Length (in km): 3.330

Damage Length (in km): 0.380

Damages Location/Chainage:

Name of Scheme/Programme:

FDR

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

BT

a)

Condition of Surfacing

S

Description of observation :

Good condition

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

Pmc - 20mm thickness

c)

Quality of Construction Material Used

S

Description of observation :

Good.

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

S

Description of observation :

No defect

e)

Compaction of flanks/ slope & raincuts

S

Description of observation :

at few place, raincut found, needs to be maintained

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Provision of one Box Culvert 1x5m x 3m.

Remark if any:

Deck slab complete, ^{w/c} Approach is in Progress.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer:

Mathesh pd gupta

Designation:

EE, RWD, Regional Leeb
puzneer

MB
23/06/2021
(Signature)

Mathesh
23/6