

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Dhup Shikha pura Se Baddiha hote hue Khushpuri tal
 Hazards: Flood/Rain
 Division: Musheara District: Gorakhpur Actual Length (in km): 1.90
 Damage Length (in km): 0.475 Damages Location/Chainage:

Name of Scheme/Programme:
 Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	

Description of observation : B.T. work not started

b) Adequate Thickness of pavement layers constructed

Description of observation : SM Gr. III was just started a prior to the inspection.

c) Quality of Construction Material Used S

Description of observation :

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. N/A

Description of observation :

e) Compaction of flanks/ slope & raincuts —

Description of observation : Not started.

2	Cross Drainage Structure
a)	Condition of head walls in Hume pipe culverts
b)	Condition of Vent Clearance
c)	Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: No trace of road breach was found.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

23-06-21

23-06-21
AE