

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Dadaha Kailash P.C.C. Path Se Mahrauli Muhudeli + tola
 Hazards: Flood/Rain note here Affected Bank side.
 Division: Maharua District: Susem Actual Length (in km): 2.47
 Damage Length (in km): 0.023 Damages Location/Character:

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement:

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	

Description of observation : Not start

b) Adequate Thickness of pavement layers constructed

Description of observation : Not start

c) Quality of Construction Material Used

Description of observation :

d) Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

e) Compaction of flanks/ slope & raincuts

Description of observation : Not started

2 Cross Drainage Structure N.A

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation, of CD works : N.A.

Remark if any: Initial restoration work done agreed with the estimate. Final restoration required in 50M length.

Overall Rating

Upto Work done Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature) 23.06.21

23/6/21
HE