

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Sananpatti to Navtoli Path

Hazards: Flood/Rain

Division: Phulpur District: Madhubani Actual Length (in km): 2.90 Km.

Damage Length (in km): 0.720 Damages Location/Chainage: 0.20 Km to 0.29 Km & 2.00 Km to 2.690 Km.

Name of Scheme/Programme: Sananpatti to Navtoli Path

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks: Yes/No

1. Pavement (BT/CC) BT

a) Condition of Surfacing Good (S)

Description of observation : BT thickness & width is as per specification

b) Adequate Thickness of pavement layers constructed YES (S)

Description of observation :

c) Quality of Construction Material Used Good.

Description of observation : Construction material used as per specification

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. - NA -

Description of observation :

e) Compaction of flanks/ slope & raincuts To be completed

Description of observation : E/W in flanks & compaction of flanks to be completed.

2. Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

☒ Satisfactory (S) / ☐ Unsatisfactory (U)

Satisfactory

Name of Officer: Ram Kumar Mishra.

Designation: E.E. R Lab Gultzar bag Patna

(Signature) [Signature]