

Inspection Report For Flood Damage Work

Date :

1 Name of PIUs : - Gopalgarh - 2

2 Name of Block/Road : Baikunthpur / Kurri Tola Baramasthan Hole kua
Nahas Talq.

A For Road

1 Damage Location / Chainage : 0 to

2 Damage Length : 126 m

3 Nature of Damage : Heavy Rain / Flood.

4 Details of Restoration Works:

i. Material being used in Restoration Works: Brick Bats

ii. Equipments / Tools being used in Restoration Works: JCB, Tractor, Trolly, Belch, Shovel

iii. Procedure taken up in Restoration Works: Yes

iv. Restored Length: 126 m

B For Bridge

N/A

1 Damage Location / Chainage:

2 Damage Length:

3 Nature of Damage:

4 Details of Restoration Works:

i. Material being used in Restoration Works :

ii. Equipments / Tools being used in Restoration Works :

iii. Procedure taken up in Restoration Works:

iv. Restored Length :

Signature
24/11/2020
IE

Signature
24/11/2020
AE

Signature
24/11/20
11/01/21
Executive Engineer
(Name of Inspector)
R.W.D. W.D.
Hathua



ग्रामीण कार्य विभाग

Rural Works Department, Govt. of Bihar

FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR
DISTRICT :- GOPALGANJ
BLOCK :- BAIKUNTHPUR

Kurmi Tola Brahmathan Hote Hue Nahar Tak

ESTIMATED COST - RS. 1550200.00

SUBMITTED BY :-
EXECUTIVE ENGINEER
RWD (W) DIVISION
GOPALGANJ-2

Report

Name of Work :- Motorable work of Kurmi Tola Brahmathan
Hote Hue Nahar Tak

Estimated Cost :- 1550200.00

Total length of Road :- km


Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.


25/10/2020
J.E.


25/10/2020
A.E.


25/10/20
E.E.

**etailed Estimate For Motorable Work in Road from Kurmi Tola Brahmathan Hote
Hue Nahar Tak damaged due to Heavy rain/flood for year 2020-2021**

Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
Providing brick bats billed in ditches including all cost of labour & material with all complete job.								
CH - 0 M to 1300 M	1	11.00	3.20	1.50	52.80	M3		
	1	6.00	1.20	0.80	5.76	M3		
	1	4.00	1.20	0.30	1.44	M3		
	1	13.50	6.00	3.00	243.00	M3		
	1	6.00	2.10	0.60	7.56	M3		
	1	14.00	4.00	0.65	36.40	M3		
	1	23.00	3.00	1.00	69.00	M3		
	1	8.00	5.00	0.60	24.00	M3		
	1	16.00	6.00	1.50	144.00	M3		
	1	5.00	4.90	0.60	14.70	M3		
	1	20.00	1.20	1.40	33.60	M3		
Less for H.P.	0.79	1.23	1.23	5.00	0.00	M3	2411.11	1525081.2
					632.26		2427.65	1534905.99
Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	0	2.50			0.00	M	2744.50 4159.56	0.00
								1525081.2
								1534905.99
Add 1 % Contingency								15250 15349.06
							Total	1550255.05
							Say	1550200.00

Rs. 15403512
Bam/Rs 15.403 lac

[Signature]
25/10/2020

J.E.

[Signature]
25.10.2020

A.E.

[Signature]
25/10/20

E.E.

Technically Approved for Rs 15.403 lac (Rupees Fifteen Lac. Forty Thousand.
& Three Hundred) only

[Signature]
21/10/21
Superintending Engineer
RWD Works Circle, Siwan