

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Er Sanjeev Kumar, E.E.

2. Name of Block - Mahua

3. Name of Road/Bridge - Judhan Chok To Parmanandpur Lal

A. for Road

1. Damage Location/Chainage : CH 2110 M

2. Damage Length : 36m

3. Nature of Damage : Flood in Baga River

4. Details of Restoration Works :

i. Material being used in Restoration works : Shama

ii. Equipments/Tools being used in Restoration Works : JCB, TRACTOR, ROLLER

iii. Procedure taken up in Restoration works :

iv. Restored Length : 36m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :


4. Details of Restoration Works :

i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :


J.E. 25/12/2020

A.E. 25/12/2020


25/12/2020
Executive Engineer,
R.W.D. Works Division,


Signature
(Name of Inspector)