

FDR-2020-21

Nlw - NH-31 To Asha Tola.

Schedule XLV Form N.134.

P.W.D.

Nawgachhiya.

DIVISION

Narayanpur.

SUB DIVISION

MEASUREMENT BOOK-591

प्रमाणित किया जाता है कि
मापी पुस्त संख्या 591 में मशीन
मुद्रित कुल 100 (एक सौ) पेज
अंकित हैं। यह मापी पुस्त श्री
नरेन्द्र कुमार सहायक अभियंता
कार्य अवर प्रमण्डल नरायणपुर के
नाम FDR योजनाओं के कार्य हेतु
निर्धारित किया जाता है।

R. W. D. W. D. Naugachia
Executive Engineer
R. W. D. W. D. Naugachia
12/11/2020

Schedule XLV Form No. 134

.....DIVISION

.....SUB-DIVISION

MEASUREMENT BOOK

Name of Office.....

Date of first entry.....

Date of last entry.....

(These four lines should be repeated and the commencement of the measurement relating to each work.)

 82.96 m^3

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
	Final Bill				
Name of work -	Temporary Restoration				
	work in nrb 31 To Asha Tola.				
Block -	Narayanpur.				
Agency -	Departmental				
Authority -	E.E. R.W.D. work Division				
	Nauga Utiya.				
Date -	21/01/2021				
	ABSTRACT OF COST				
①	Providing Brick bats				
	including spreading				
	laying hand packing				
	and Compacting				
	etc				
	same qty vide Trac				
	9 term 1/2 Page - 1/2				
	$185.71 \text{ m}^2 @ 1718.47 / \text{m}^2 = \text{Rs } 319137 = 00$				
	$\text{Add G.S.T @ 12\%} = 38296 = 00$				
	$\text{Add L.E.S @ 1\%} = 3191 = 00$				
	$\text{Add S.F @ 10\%} = 19741 = 00$				
	Rs 3,80,365 = 00				
<u>Utiya.</u> <u>21/01/2021</u> <u>J.E</u>	<u>21/01/21</u> <u>OB</u>				
	<u>Ref</u> <u>20/3/2021</u>				
	<u>Executive Engineer</u> <u>R. W. D., W. D. Nauga Utiya</u>				

Inspection Report For Flood Damage Work

Date :- 26/02/2021

1. Name of PIU - Executive Engineer, R.W.D. - W.D. - Naugachhiya.

2. Name of Block/Road :- Nawanganpur / NH-31 TO Asha Tola.

A. For Road

1. Damage location/Chainage m - 0-100m, 100-500m, 500-1000m, 1000-1500m, 1500-2000m

2. Damage length 58m, 18m, 52m, 57m, 14m

3. Nature of Damage Erosion by Flood water.

4. Details of Restoration Works

(i) Material being used in Restoration Works: Brick Bats.

(ii) Equipment's/Tools Being used in Restoration Works:

(iii) Procedure Taken up in Restoration Works:

(iv) Restored Length: 199m (not Filled with Brick bats)

B. For Bridge

1. Damage Location/Chainage

2. Damage length

3. Nature of Damage

4. Details of Restoration Works

(i) Material being used in Restoration Works:

(ii) Equipment's/Tools Being used in Restoration Works:

(iii) Procedure Taken up in Restoration Works:

(iv) Restored Length:

C. Requirement of New CD/Bridges

(I) Name of Road:

(II) Location/Chainage

(III) Type of CD Work/Length required

Notes:-

- Upload one Photograph of damaged portion if available
- Attach minimum Two Photograph (during restoration & after restoration) photographs should be Geotags and at Least one Photo be captured in selfie mode.
- Restoration work has been done during flood season, but at present exact measurement can't be possible as per actual work done.

26/02/2021
JE

Signature of JE/AE/EE

26-02-2021
AE

Executive Engineer
R. W. D., W. D. Naugachhiya

Signature

(Name of inspector)

26/02/21
AE

26/02/21
AE

26/02/21