

Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- *Ram Ratan Ram*
2 Name of Block :- *Udalgurh*
3 Name of Road :- *Defection of 8th mile for temporary Restoration of Cokshimpr Rameswar to Mayfoz.*

A. For Road

- 1 Damage Location/Chainage :- *4.40 km to 4.50 km, 6.80 km to 7.90 km*
2 Damage Length :- *1.20 km*
3 Nature of damage :- *poor crust*
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-
- Bricks laid*

B. For Bridge

- 1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

P. S. S. S.
JE

A. S. S.
AE

E. S. S.
EE

9/1/2021
Signature
(Name of inspector)

1

(These four lines should be repeated at the commencement of the measurement relating to each work)

[illegible]Continuation
T-3-24

225.17ms

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		18.17		225	125m ³
1x20.6	x2.6	x0.15			10.80
1x15.6	x3.40	x0.20			10.20m ³
2x25.6	x1.20	x0.20			12.00
2x40.6	x1.10	x0.25			22.00
1x30.6	x3.75	x0.30			33.75
1x30.6	x4.6	x0.25			30.00
1x25.6	x3.75	x0.25			23.43
1x30.6	x4.6	x0.30			36.6
1x24.6	x3.6	x0.25			21.60
2x25.6	x1.50	x0.25			18.75
2x15.6	x3.40	x0.20			20.00

1x30.6	x4.6	x0.30			36.6
4x25.6	x1.50	x0.25			37.50
2x18.6	x1.30	x0.20			14.56
1x10.6	x1.50	x0.20			8.00
5x16.6	x1.40	x0.20			36.6
11x4.6	x2.6	x0.25			22.00
8x8.6	x1.20	x0.20			25.36
15x2.6	x2.6	x0.30			18.00
8x4.6	x2.6	x0.30			19.20
1x4.6	x2.6	x0.25			14.00
4x10.6	x1.50	x0.20			12.40
Total					700.76

Handwritten signature
15/10/16

Handwritten signature
Continuation slip

Sch. XLV-Form No. 134

Pong ~~cap~~
 15/1/2024
 TE

Am
 15/1/2024
 AE

cap
 15/1/2024

Scanned by CamScanner