## Inspection Report for Flood Damage Work

1. Name of PIUs - E. E. R. W.D., Na Lug. 2 Name of Block/Road - pateper, Mauwachak to Khap A. Fer Road 1. Damage Location/Chainage . 2. 10 km, 2. 15 km, 2. 55 lemo-2. Damage Length 3. Nature of Damage Flood. Material being used in Restoration works: Brick both, Sand 4. Details of Restoration Works Equipments/Tools being used in Restoration works: ii. Procedure taken up in Restoration works: ili. Restored Length iv. B. For Bridge 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works Material being used in Restoration works: Equipments/Tools being used in Restoration works: ii. Procedure taken up in Restoration works: iii. Restored Length iv.

Signature of JE/AE/EE

(Name of Inspects