

Inspection Report for Flood Damage Work

Date

1. Name of PUs - E & R.W.D. Haryana
2. Name of Block/Road - Bhagpur, House of Abdul Kishor
- A. For Road Sub to house of Rajender Sub.
1. Damage Location/Chainage CH 0/120M to 0/150M
2. Damage Length 30M
3. Nature of Damage Flood
4. Details of Restoration Works
- Material being used in Restoration works: Brick Bats.
 - Equipments/Tools being used in Restoration works:
 - Procedure taken up in Restoration works:
 - Restored Length:

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE
8.10.20

Signature
6/10

Signature
7/10
(Name of Inspector)