Inspection Report for Flood Damage Work

- 4		٠.

- E.E R. IN. D Hazipus 1. Name of PlUs -
- 2. Name of Block/Road Bhaqueanpus, Bhaqueanpusto Totalia via
- 1. Damage Location/Chainage

1st km d 3 rd km

2 Damage Length

3. Nature of Damage

4. Details of Restoration Works

- Material being used in Restoration works: Brick bouts.
- Equipments/Tools being used in Restoration works: 11.
- ili. Procedure taken up in Restoration works:
- Restored Length iv.
- B. For Bridge
- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works:
 - ii. Equipments/Tools being used in Restoration works:
 - Procedure taken up in Restoration works:
 - Restored Length

Signature of JE/AE/EE

(Name of Inspect).