

Inspection Report for Flood Damage Work

Date: - 15/12/2020

1. Name of PIUs - HAJIPUR

2. Name of Block/Road - HAJIPUR

A. For Road

Hanuman Mander Jachua Pokhar to Ghandhi Setu

1. Damage Location/Chainage : 4th Pally No - 1 0.840 km to 0.955 km

2. Damage Length : 155 m

3. Nature of Damage : Flood

4. Details of Restoration Works :

i. Material being used in Restoration works : Local Sand and Brick bats

ii. Equipments/Tools being used in Restoration works : JCB, Roller,

iii. Procedure taken up in Restoration works :

iv. Restored Length : 155 m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature of JE/AE/EE
15.12.20
AE

Signature of JE/AE/EE
15/12
E.E

Signature of JE/AE/EE
15/12
(Name of Inspector)
प्र.का.वि. कार्य
प्र.का.वि. कार्य